


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	06/05/2012	1840		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #6	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	06/05/2012 0900
	Position:	Operations Section Chief	To:	06/05/2012 1745
7. Personnel Roster Assigned				
Name	ICS Position	DUTY CELL		
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Kevin Johnson	SOTF#6			
8. Activity Log				
Activity Area	MP 37.50 upstream of delta control point	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team 6 Activity:</u></p> <p>SOTF#6 Kevin Johnson (START), Enbridge Team Lead Loren CaSale, and Leica operator Amber McDougal performed poling at 55 total locations. A total of 10 locations had an overall submerged oil category of heavy, 17 locations had an overall submerged oil category of moderate, and 15 locations had an overall submerged oil category of light. Thirteen (13) locations indicated no signs of submerged oil.</p> <p>Generally, more light oil sheen was observed along areas of sand substrate with more moderate and heavy oil sheen observed along silt/soft substrate. Globules up to 1.5 cm were identified in locations having soft and silt based substrate.</p> <p>All locations SOTF #6 visited registered above the minimum temperature requirement of 60 degrees F. Observed temperatures ranged from 60.3 to 72.7 degrees F.</p> <p>Poling operations were not significantly impacted by vegetation or environmental conditions within focus areas. SOTF#6 was able to successfully navigate to all tasked poling reassessment locations.</p>			
Health and Safety	None			

Issues	
Comments	